

Unzip INC-1610_update.zip and run INI_FCFG_V3.23.exe

MPWIN – Manufacturing Test Program




INIC-1610/1605

Download Firmware and select firmware file

- 1) 1610P_Combo_V300.bta for **NST-360SU and NST-300SU**
- 2) 1610P_Combo_V108RC1.bta for **NST-D100SU**

Click “Start” to update firmware



Please follow the next few steps carefully.

- 1) Once the update has been complete,
(DO NOT close the program as this program is needed for the next step.)
- 2) Please disconnect the USB cable from the back of the unit.
(DO NOT power off the unit, leave unit powered ON)
Wait 5 Seconds and then reconnect the USB cable back into the unit.
- 3) The program should automatically rerun the update again.

Once the second pass has been complete, the unit is now fully updated to support 3TB hard drives.

You may now close the program and power off the unit.

